

**DEPARTMENT OF TRANSPORTATION**

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch  
690 Walnut Ave.St. 150  
Vallejo, CA 94592-1133  
(707) 649-5453  
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:**Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-018808**Date Inspected:** 18-Dec-2010**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Li Yang**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG Segment**Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance (QA) Inspector Mr. M. Manikandan was present during the time noted above for observations relative to the work being performed.

**OBG # TRIAL ASSEMBLY YARD (CB16)**

This QA Inspector along with QA Inspector Mr.Manjunath S Math performed dimensional joint survey inspection to verify the gap between the skin plates of Cross Beam to the Segment 11DE FL3. The measurements were recorded on a separate sheet and forwarded to team leader for review and disposition. The cross beam and panel point designations were as follows:

CB16- PP 104 and PP 106

This QA Inspector randomly observed the following work in progress:

**OBG # TRIAL ASSEMBLY YARD (12AW-12BW)**

The QA Inspector observed the welding operation per the SMAW process on weld joint no. 001 in the (1G) flat position on bottom and side panel piece mark no. SEG3004A. The location was the complete joint penetration groove weld joining side and bottom panel of segment 12AW at work point W3. The welder ID was 040611. The welding variables recorded by QC appeared to comply with the WPS-B-P-2214-B-U2-FCM-1.

---

## WELDING INSPECTION REPORT

( Continued Page 2 of 3 )

---

The QA Inspector observed the welding operation per the SMAW process on weld joint no. 003 in the (1G) flat position on bottom and side panel piece mark no. SEG3005A. The location was the complete joint penetration groove weld joining side and bottom panel of segment 12BW at work point W3. The welder ID was 040611. The welding variables recorded by QC appeared to comply with the WPS-B-P-2214-B-U2-FCM-1.

### OBG # TRIAL ASSEMBLY YARD (12AW-12BW)

The QA Inspector observed the welding operation per the SMAW process on weld joint no. 004 in the (1G) flat position on bottom and side panel piece mark no. SEG3004A. The location was the complete joint penetration groove weld joining side and bottom panel of segment 12AW at work point W4. The welder ID was 046709. The welding variables recorded by QC appeared to comply with the WPS-B-P-2214-B-U2-FCM-1.

The QA Inspector observed the welding operation per the SMAW process on weld joint no. 004 in the (1G) flat position on bottom and side panel piece mark no. SEG3005A. The location was the complete joint penetration groove weld joining side and bottom panel of segment 12BW at work point W4. The welder ID was 046709. The welding variables recorded by QC appeared to comply with the WPS-B-P-2214-B-U2-FCM-1.

### OBG # TRIAL ASSEMBLY YARD (12AE)

The QA Inspector observed the welding operation per the SMAW process on weld joint no. 021 in the (4G) overhead position on deck and edge panel piece mark no. SEG3001AA. The location was the complete joint penetration groove weld joining edge and deck panel of segment 12AE at work point E5. The welder ID was 050289. The welding variables recorded by QC appeared to comply with the WPS-B-P-2214-Tc-U4b-FCM-1.

### OBG # TRIAL ASSEMBLY YARD (12BE)

The QA Inspector observed the welding operation per the SMAW process on weld joint no. 001 in the (4G) overhead position on deck and edge panel piece mark no. CA3002. The location was the complete joint penetration groove weld joining edge and deck panel of segment 12BE at work point E5. The welder ID was 050289. The welding variables recorded by QC appeared to comply with the WPS-B-P-2214-Tc-U4b-FCM-1.

### OBG # TRIAL ASSEMBLY YARD (12AW-12BW)

The QA Inspector observed the welding operation per the SAW process on weld joint no. 001 in the (1G) flat position on deck panel piece mark no. OBW12D. The location was the transverse splice weld joining segment 12AW and 12BW at work point W5 to W2. The welder ID was 042195. The ZPMC CWI was identified as Li Yang. The welding variables recorded by QC appeared to comply with the WPS-B-T-223(2)1T-ESAB.

The QA Inspector observed the welding operation per the SAW process on weld joint no. 001 in the (1G) flat position on deck panel piece mark no. OBW12D. The location was the transverse splice weld joining segment 12AW and 12BW at work point W5 to W2. The welder ID was 044560. The ZPMC CWI was identified as Li Yang. The welding variables recorded by QC appeared to comply with the WPS-B-T-223(2)1T-ESAB.

For additional information please reference the pictures below:

---

## WELDING INSPECTION REPORT

( Continued Page 3 of 3 )

---



### Summary of Conversations:

No relevant conversations were reported on this date.

### Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang 15000422372, who represents the Office of Structural Materials for your project.

---

<b>Inspected By:</b>	Manikandan,Murugan	Quality Assurance Inspector
<b>Reviewed By:</b>	Peterson,Art	QA Reviewer

---